TABLE #1

ASBESTOS - SUSPECT MATERIAL DATA SHEET (Description, Finding, & Assessment)

Project Name:	FLETC Building 94 Asbestos Survey

Site: FLETC, Glynn County, GA Building: Building 94
Inspector Name: R. Mannebach, L. Miles Date: 3/24/00

Suspect	Material Description	Quantity	Location	Present	Potential	Asbestos	Hazard
Mat. No.	(Category=Surf, TSI,	(approx.)*	Ref. Drawing	Condition	Disturb.	Finding	Assess.
	Misc)		No.			(P or N)	(7-1)
1	12" Beige Floor Tile	28,500 sf	Throughout	NF, G	PSD	P	3
	(Misc)		Fig. 1				
2	Mastic Beneath 12"	28,500 sf	Throughout	NF, G	LPD	P	1
	Beige FT (Misc)		Fig. 1				
3	Fiberboard	1,950 sf	Mezz D&F	NF, G	PD	N	N/A
	(Misc)		Fig. 1				
4	Soundboard	1,950 sf	Mezz D&F	NF, G	PD	N	N/A
	(Misc)		Fig. 1				
	Mastic beneath	1,950 sf	Mezz D&F	NF, G	PD	P	2
	Soundboard (Misc)		Fig. 1				
6	2" Pipe Insulation	1,200 lf	Mezz D&F	F, D	PD	N	N/A
	(TSI)		Mech Rm				
			Fig. 1				
7	Duct Insulation	1,500 sf	Mezz D&F	F, G	PD	N	N/A
	(TSI)		Fig. 1				
8	4" Pipe Insulation	1,200 lf	Mezz D&F	F, D	PD	N	N/A
	(TSI)		Mech Rm.				
			Fig. 1				
9	4" Elbow Fitting	40 - 50	Mezz D&F	F, D	PD	N	N/A
	(TSI)	fittings	Mech Rm				
			Fig. 1				
10	12" Pipe Fitting	10 - 15	Mech Rm	F, D	PD	N	N/A
	(TSI)	fittings	Fig. 1				
11	Hot Water Tank	800 sf	Mech Rm	F, G	PD	N	N/A
	Insulation (TSI)		Fig. 1				

^{*} All quantities are approximate and should be field verified by the abatement contractor prior to cost estimating.

Present Condition

 $F \hspace{1cm} = Friable \hspace{1cm} G \hspace{1cm} = Good \hspace{1cm} (Very \hspace{1cm} localized \hspace{1cm} limited \hspace{1cm} damage)$

 $NF \hspace{1cm} = Nonfriable \hspace{1cm} D \hspace{1cm} = Damaged \hspace{0.1cm} \text{(Damage of less than 10\% distributed and less than 25\% localized)}$

SD = Significantly Damaged (Damage equal to or greater than 10% distributed /

25% localized)

Potential for Future Disturbance

LPD = Low Potential for Disturbance (Contact, Vibration, and Air Erosion all of Low Concern)

PD = Potential for Damage (Contact, Vibration, or Air Erosion of Moderate Concern)

PSD = Potential for Significant Damage (Contact, Vibration, or Air Erosion of High Concern)

Asbestos Finding P = Positive N = Negative

Hazard Assessment = 7 thru 1

(7 being the worst i.e. significantly damaged material)

Page <u>1</u> of <u>1</u> Attachment #34